

25X1A 25X1A 25X1A

25X1A

25X1A 25X1A 25X1A

BLACK SHIELD CHECK LIST (as of 18 Aug 67) Msn Nr BX 6732
 H-hour 28/0230 Z 1130 L Page 2 of 2

H-Minus	ACTION	DOI	RESP INDV	TIME DUE(Z)	TIME DUE(L)	TIME DONE(L)	DONE BY (Initials)
-10:00	Send [REDACTED] (Terminal wx fcsts)	B-5	B	27/1630	10130	0250	JY
-9:00	Rcv [REDACTED] (GO-NO GO wx fcsts)	B-11	B	1730	0230	0200	JY
-9:00	Give [REDACTED] input to Msn Coord	B-23	B	1730	0230	0200	JY
25X1A	Plot 12Z RODN & [REDACTED] RAOBs		Y	1700	0200	0200	MY
-8:00	Send [REDACTED] (thru L-hr, if read)	B-16	B,A	1830	0330		
	Plot 12Z 30Mb Chart		Y	1800	0300	0320	SE
	Brief tankers & annotate 175's	B-24	C				
-4:00	Send [REDACTED] (Terminal wx fcsts)	B-5	C	2230	0730	0630	DM
-4:00	Send [REDACTED] (Met Watch obs)	B-18	Z	2230	0730	07	SE
-3:50	Update [REDACTED]		Z,X	2240	0740	0740	RAH
	Brief tankers & annotate 175's	B-24	C				
-3:30	Brief pilots and ops staff	B-20	A	2300	0800	0800	DEB
25X1A	Brief tankers & annotate 175's	B-24	C				
-3:00	Rcv [REDACTED] Amend (GO/NO GO fcsts)	B-11	A	2330	0830	0734	DEB
-3:00	Rcv Letdown Plates from DCO	B-14	A	2330	0830	0830	DEB
-1:50 -3:00	Enter fcsts on Letdown Plates	B-14	A,C	28/0040	0940	0900	DEB
-2:30	Msn Obsvr to CP; posts data	B-13	X	0000	0900	0900	RAH
25X1A	Rcv [REDACTED] (Wx Scout reports)	B-22	A	0030	0930	(BY XCPN)	DEB
	#7691 (if needed for local & SE)			2330	0830	0830	SE
	Get ESSA-2 Pictures ASAP #7692		Z,C	0100	1000	0950	SE
-1:40	Msn Fcstr to CP; Obsvr to wx stn	B-13	A,X	0050	0950	1030	DEB
-1:35	Letdown Plate fcsts to pilots (Notify Mission Coordinator)	B-14	A	0055	0955	—	
-1:30	Notify DCOL (If need to rebrief pilots)	B-20	A	0100	1000	—	
-1:10	Rebrief pilots if necessary	B-20	A	0120	1020	—	
25X1A	Get [REDACTED] Pictures ASAP #7068		C,X	0400 0600	1300 1500	111	
L-Plus	Landing time	Z	L				
+0:15	Return Met Watch to wx station	B-13	X			1550	JY
+0:15	Start debriefing form	B-15	A			1519	JY
+0:45	Attend pilot debriefing	B-15	A			1605	JY
25X1A	Give [REDACTED] input to DCOM Coord ASAP after debriefing	B-15	A	ASAP	ASAP	1610	JY
+24:00	Turn in Msn Wx File to Intell	B-17	A				

25X1A 25X1A 25X1A

BLACK SHIELD CHECK LIST
(As of 18 Aug 67; with tankers)

Page 1 of 2

Mission Nr BX6732Date 28 OCT 67H-hour 0230 Z 1130 LL-hour 0638 Z 1538 LCode Name BLACK SHIELD

Key Personnel	DCOW Personnel	Duty Hours	25X1A
Msn Pilot	A Fcstr	27/0800-1500L; 28/0600-1800L	
Spare Pilot	B Fcstr	27/1500-28/0100L	
Chase Pilot	C Fcstr	28/0100-1000L; THEN REST LOUNGE STANDBY (ERF)	
Commander	X Obsvr	27/1000-1800L; 28/0700-1700L	
Msn Coord	Y Obsvr	27/1800-28/0300L	
Msn DCOM	Z Obsvr	28/03-1100L	25X1A
Msn TTFC	<u>EMGCY RCVRY FCSTR</u>		

H-Minus		RESP DOI	TIME INDV	TIME DUE (Z)	TIME DUE (L)	TIME DONE (L)	DONE BY (Initials)
-24:00	Start this check list	B-3	A	27/0230	27/1130	1130	DEB
-24:00	Arrange work schedule	B-4	A	0230	1130	0930	DEB
-23:30	Attend Commander's Briefing	B-1	A	0300	1200	1200	DEB
-23:00	Rcv [REDACTED] (Prelim Ops Data)	B-1	A	0330	1230	0630	JY
	Rcv Wx Scout CALL SIGNS [REDACTED]					1700	DEB
	Give Msn Planning Fcst to TTFC		C				25X1A
	Give [REDACTED] Crews Prelim Brfg	B-2	C	0300	1200		25X1A
	Give [REDACTED] Crews Prelim Brfg	B-2	C	0400	1300		25X1A
	Coordinate Further TTFC Support	B-2	C	0430	1330		
-21:00	Rcv [REDACTED] (Tmn1 fcsts)	B-5	A	0530	1430	1346	DEB
-20:00	Start Met Watch on wall map	B-21	A	0630	1530	1630	JY
-21:00	Rcv [REDACTED] (Mission wx data)	B-6	A	0530	1430	1357	DEB
	Get ESSA-2 Pictures #7679 #7680	B-10	X	0300	1200	1130	RAH
	Get [REDACTED] Pictures #7054 #7055	B-10	X	0530	1530	1530	RAH
	Rcv [REDACTED] (Composite rte data)	B-6	A	Vrbl	Vrbl	2032	JY
-17:30	Rcv [REDACTED] Amend (Mission wx)	B-6	A	0900	1800		25X1A
-17:15	Rcv [REDACTED] (Tmn1 fcsts)	B-5	A	0915	1815	1700	JY
-17:00	Brief pilot and ops staff	B-7	A	0930	1830	1830	JY
-17:00	Rcv LIST OF PRIMARY & SECONDARY ALTS			0930	1830	0710	JY
-14:00	Rcv [REDACTED] (Tanker msn wx fcst)	B-9	B	1230	2130	2100	J25X1A
	Turn on [REDACTED]		Y	1200	2100	2100	JY
	App [REDACTED] (For Release 2001/04/02 : CIA-RDP69B00041R001100010011-4)			1230	2230	2105	J25X1A